INSTALLATION INSTRUCTIONS



OUTLAW NERF STEP BARS

APPLICATION:

2005-2019 Toyota Tacoma Double Cab

PART NUMBER: 58-52775

			CONTENT		
ITEM	QUANTITY	NTITY DESCRIPTION			TOOLS NEEDED
1	1	DRIVER STEP BAR ASSEMBLY			13MM SOCKET
2	1]	PASSENGER STEP BAR ASSEMBLY		
3	1	DI	DRIVER FRONT MOUNTING BRACKET		16MM SOCKET
4	1	PASS	PASSENGER FRONT MOUNTING BRACKET		16MM WRENCH
5	1	DR	DRIVER CENTER MOUNTING BRACKET		
6	1	PASS	PASSENGER CENTER MOUNTING BRACKET		
7	1	D	DRIVER REAR MOUNTING BRACKET		
8	1	PASSENGER REAR MOUNTING BRACKET			
9	12		M8 HEX HEAD CAP SCREW		
10	12		M8 SPLIT LOCK WASHER		
11	12		M8 FLAT WASHER		
12	12		M10 HEX HEAD CAP SCREW		
13	12		M10 BELLVILLE WASHER		
14	12		M10 SERRATED FLANGE NUT		
ANTI-SEIZE LU	JBRICANT MUS	BE USED ON ALL S	TAINLESS STEEL FASTENE	RS TO PREVENT THREAD	DAMAGE AND GALLING
Passenger Side • © ITEM 1	Opposite 9 9 9 9 9 6 6 6 6		■		ITEM 3
		<u> </u>			

ITEM 5

ECO #: W18-0157

ITEM 8


ITEM 4


ITEM 6

ITEM 7


PROCEDURE


- 1. Remove contents from box, verify if all parts listed are present and free from damage. Carefully read and understand all instructions before attempting installation.
 - Failure to identify damage before installation could lead to a rejection of any claim.
- 2. Start installation on either side of the vehicle. Locate mounting locations with factory threaded holes with caps covering them. Remove factory caps from threaded holes, they will not be used again. Locate (1) Front Mounting Bracket and loosely install it to the front mounting location on the rocker panel using (2) Long M8 hex head cap screw, (2) M8 split lock washer, and (2) M8 flat washer. Locate the Center and Rear Mounting Brackets (Item 3) and loosely secure in the correct mounting locations on the rocker panel. Loosely install using the provided M8 hardware. See Figure. 1 and 2.
- 3. Repeat Step 2 for the other vehicle side.






- 4. For step bar installation, use the supplied M10 Hardware to loosely secure the step bar to the preinstalled brackets. See **Figures 3 & 4**. *Note: All brackets install similarly to step bar*.
- 5. Align and adjust the step bars and brackets as needed, then fully tighten all hardware: M8 to 18 ft-lbs, M10 to 38 ft-lbs.









CARE INSTRUCTIONS

- REGULAR WAXING IS RECOMMENDED. DO NOT USE ANY TYPE OF POLISH OR WAX THAT MAY CONTAIN ABRASIVES.
- STAINLESS STEEL PRODUCTS CAN BE CLEANED WITH MILD SOAP AND WATER. STAINLESS STEEL POLISH SHOULD BE USED TO POLISH SMALL SCRATCHES.
- GLOSS BLACK FINISHES SHOULD BE CLEANED WITH MILD SOAP AND WATER



Westin Automotive Products, Inc. 320 W. Covina Blvd San Dimas, Ca. 91773





WARNING



Failure to follow these instructions could lead to death, personal injury, and / or property damage.

Failure to follow these instructions could lead to death, personal injury, and / or property damage.

FASTENERS:

All Westin supplied fasteners must be utilized and installed in accordance with the installation instructions and apply torque to the specifications as defined. DOUBLE CHECK ALL FASTENERS BEFORE INITIAL USE, AND PERIODICALLY IN THE FUTURE TO ENSURE PROPER FUNCTION AND SAFETY.

DRILLING:

Most Westin products do not require drilling for installation. If drilling is defined as required, use caution when drilling a vehicle. FAILURE TO REVIEW AN AREA TO BE DRILLED MAY RESULT IN PERSONAL INJURY AND/OR INJURY TO OTHERS AS WELL AS VEHICLE DAMAGE.

EYE PROTECTION:

ALWAYS WEAR SAFETY GLASSES OR GOGGLES DURING THE INSTALLATION PROCESS TO AVOID PERSONAL INJURY.

MAXIMUM TOWING/CARRYING CAPACITY: (if applicable)

The Westin Receiver Hitches will have a visible tow rating label affixed directly on the product. User should never exceed the vehicle manufacturers maximum tow and weight rating regardless of the capacity of the hitch. FAILURE TO FOLLOW THESE GUIDELINES WILL VOID THE WESTIN WARRANTY AND MAY RESULT IN PERSONAL INJURY AND/OR INJURY TO OTHERS AS WELL AS VEHICLE DAMAGE.

FOR CALIFORNIA RESIDENTS ONLY-PROP 65 WARNING:

Some products may contain chemicals such as DEHP, which can cause cancer, birth defects or other reproductive harm. For more info go to www.p65warnings.ca.gov