


Installation Guide 2019 Chevrolet Silverado / GMC Sierra


with Multi-Pro Step option




Product Code 223-224-225-226


This Tonneau Cover may retract to the full open position very quickly resulting in any objects placed on top of the Tonneau Cover to fall off the Tonneau or become trapped inside of the Tonneau carrier. Do not place ANY objects on top of the Tonneau Cover when attempting to close. Failure to follow the instruction may result in damage to your vehicle, belongings or Tonneau Cover. To avoid injury keep all body parts clear of Tonneau Cover and carrier when opening.








Tools Needed

































Troubleshooting

Cover is hard to pull or retract.

rag and top gas


Spray 303[®] on a rag and wipe the top gasket in the Track back and forth.



Cover does not latch.




Check Track to Track measurement.



Track tips up or down.




Use shim(s) behind bracket to level Track.



Cover does not reach tailgate.




Make sure Tracks are back against tailgate.




OROLL-N-LOCK®

Any questions please call Customer Service at 800-952-7655 or email customerservice@rollnlock.com


IF TRUCK **IS** EQUIPPED WITH THE MULTI-PRO STEP PROCEED WITH PAGES 16-27







Remove back track clamp and break away tab.


DRIVERS SIDE TRACK ONLY





Key supplied track clamp bracket $\overline{\mathbb{Z}}$ onto the back of the track at the slotted hole. Using the same screw and washer that was removed loosely attach bracket to track.


























C ROLL·N·LOCK°


Any questions please call Customer Service at 800-952-7655 or email customerservice@rollnlock.com

Troubleshooting

Cover is hard to pull or retract.

Spray 303[®] on a rag and wipe the top gasket in the Track back and


forth.



Cover does not latch.




Check Track to Track measurement.



Track to Track is more than 59"




Use shim(s) behind bracket to adjust accordingly.



Track tips up or down.



Use shim(s) behind bracket to level Track.



Cover does not reach tailgate.



Make sure Tracks are back against tailgate.

